

Photo Number: 17 Photo Filename: 17_End Face of Left Truss Vertical Member

Attachment Description:
End Face of Left Truss
Vertical Member L01_U01
at Top of Sidewalk



Photo Number: 18 Photo Filename: 18_Right Truss at L04_21_DSCN5573.JPG

Attachment Description:
Right Truss at L04



Photo Number: 19 Photo Filename: 19_Right Truss above Deck from

Attachment Description:
Right Truss above Deck
from Begin



Photo Number: 20 Photo Filename: 20_Left Truss from Begin Left_21_DSCN5549.

Attachment Description:
Left Truss from Begin Left



Photo Number: 21 Photo Filename: 21_Begin Face of L03_U03 at L03 on Right

Attachment Description:
Begin Face of L03_U03 at
L03 on Right Truss



Photo Number: 22 Photo Filename: 22_Begin Face of Floorbeam 0 from

Attachment Description:
Begin Face of Floorbeam 0
from Right



Photo Number: 23 Photo Filename: 23_Begin face of floorbeam 8 and underside

Attachment Description:
Begin face of floorbeam 8
and underside of deck near
end abutment



Photo Number: 24 Photo Filename: 24_End Right Abutment

Attachment Description:
End Right Abutment
Pedestal



Photo Number: 25

Photo Filename: 25_End Abutment DSCN5563.JPG

Attachment Description:
End Abutment



Photo Number: 26

Photo Filename: 26_Begin Abutment from Left_21_DSCN5551.

Attachment Description:
Begin Abutment from Left



Photo Number: 27 Photo Filename: 27_End Abutment Joint from

Attachment Description:
End Abutment Joint from
Left



Photo Number: 28 Photo Filename: 28_End Right Abutment Bearing from

Attachment Description:
End Right Abutment
Bearing from Right



Photo Number: 29

Photo Filename: 29_Begin Left Truss Bearing_21_DSCN5548.

Attachment Description:
Begin Left Truss Bearing



Photo Number: 30

Photo Filename: 30_End Right Railing Post Anchorage Plate at

Attachment Description:
End Right Railing Post
Anchorage Plate at
Underside of Deck



Photo Number: 31

Photo Filename: 31_Left Sidewalk Railing from Begin

Attachment Description:
Left Sidewalk Railing from
Begin Approach



Photo Number: 32

Photo Filename: 32_Begin Left Wingwall_20_DSCN5553.JPG

Attachment Description:
Begin Left Wingwall



Photo Number: 33

Photo Filename: 33_Left Sidewalk Grating at Truss Member

Attachment Description:
Left Sidewalk Grating at
Truss Member L0_U1 from
End



Photo Number: 34

Photo Filename: 34_Left Sidewalk Floorbeam between L02 and

Attachment Description:
Left Sidewalk Floorbeam
between L02 and L03 from
End

